

Misrepresentation of Intertek Certified Product Labels

120 Minutes Latched Single Leaf Door Assembly & Halspan 60 Optima Fire Rated Wood Door Assembly

Notification Type:	Misuse of Certification Mark
Certification Type:	Not Intertek Certified

Notification

Intertek notifies public that we have been notified by the applicant that the labels identified below have been misrepresented as Intertek Certified.

Company Identification

Saudi Lebanese Architectural Woodworks Factory

Product Identification

A misrepresentation of certified product labels have been found for Saudi Lebanese Architectural Woodworks Factory.

120 Minutes Latched Single Leaf Door Assembly. The certification mark WH showing 22020 control number (4) labels affected are# 000049, 000071, 000072, 0000738.

Halspan 60 Optima Fire Rated Wood Door Assembly The certification mark WH showing 23623 control number (1) label # 000298.

Label Photo on Page 2.

Hazard Involved

Not Intertek Certified

What To Do

Use should be immediately discontinued and return to the point of purchase and the labels should be removed and returned to Intertek.

Published: October 22, 2025
Revised:

Public Notice ID: 2025-99
Page 2 of 2

Photos and Images

